

Date: December 2th, 2025

Print Name: Irving Salas

Inspection #: 94-20251028-0825

Signature: I.S

Company: KLUANE DRILLING LIMITED

Phone: (867)336-2109


Compliance Notification

Order Number	Compliance Due Date	Describe Work Which Was Done	Date Completed
2	2025-11-07		
3	2025-11-07		
4	2025-11-07	The KD1000-5 drilling rig ceased operations on November 3th, 2025 and is currently in a workshop in Whitehorse undergoing repair and maintenance (including rotation guard)	6/11/2025
5	2025-11-10		

4. Rotation Guard KD1000-5

It was verified in the workshop that the guard had been repaired and closed completely, covering the pipe when rotation begins.





AFTER FIX



Please submit this form to work.safe@wcb.yk.ca so that it is received on or before the compliance date. If you have any questions or concerns regarding compliance with the orders, please contact our office at (867) 667-5450 or 1-800-661-0443.

If additional space is required, please copy this form or attach sheet of paper.