

Below are some photos of evidence regarding your 3 order numbers.

Rotation guard has been installed on the angle grinder.



The rotation guard has been adjusted to cover more points of entry.



Propane tanks have been relocated into the fresh air, 100lb tanks tied to one another to prevent the risk of falling over.

